

THIS IS A TECH EVAL OF MISSION 3239. BOTH RECORDERS OPERATED PERFECTLY WITH NO INDICATION OF DECREASING SPEED. THE 420 CYCLE TONE RECORDED BY THE S BAND RECEIVER WAS DISTORTED AND NOT A TRUE SINE WAVE AS COMPARED TO THE TONE RECORDED BY THE X BAND RECEIVER. THE S BAND TONE WAS STRONG AND INTERMITTENT WHILE THE X BAND WAS WEAK AND STEADY. SIGNALS WERE INTERCEPTED BY ALL RECEIVERS. THE L BAND RECORDING HAD A CONSTANT POPPING NOISE THROUGHOUT THE ENTIRE MISSION.

END OF MESSAGE

TOP SECRET

A-PDP89R00569P0007001190077